

TEST REPORT

Report No. : MAN:HL:1048003871

DATE : 28th May, 2019



J K ENTERPRISES

9-BM 3RD FLOOR, STAR ZONE MALL, NASHI-PUNE ROAD
 NASHIK ROAD - 422101
 INDIA

CONTACT PERSON : MR. SANJAY SAHNI

THE FOLLOWING SAMPLE(S) WAS/WERE SUBMITTED AND IDENTIFIED BY/ON BEHALF OF THE CUSTOMER AS :

SAMPLE DESCRIPTION	GRAPAGE/GRAPVIN GRAPE GUARD
STYLE NO.	23.5 X 35 - 5G, 23.5 X 38 - 5G, 23.5 X 45 - 6.5G, 23.5 X 32 - 5G, 23.5X35-7G, 23.5X38-8G, 23.5X45-8G, 23.5X47-7G, 35X40-8.5G, 35X47-6.5G, 35X47-10G, 35 X 53.5 - 10G
SAMPLE RECD ON	13/05/2019
TEST PERFORMING DATE	17/05/2019 TO 27/05/2019

SUMMARY OF TEST RESULTS:

TEST REQUESTED	CONCLUSION
DIMETHYL FUMARATE (DMFU)	SEE RESULT

TEST(S) RESULT & METHOD: PLEASE REFER TO NEXT PAGE(S)

Per Pro SGS India Pvt. Ltd.



SANDIP BHUSHAN(Asst. Manager)

Email your Test Report Related Enquiries at Feedback.HLT@sgs.com

TEST REPORT

Report No. : MAN:HL:1048003871

DATE : 28th May, 2019



TEST RESULT:-

DIMETHYL FUMARATE (DMFU):

Test Method : Liquid extraction; Analysis was conducted by GC / MS.


Test Name	Result	Requirement
Dimethyl Fumarate	ND	/

Detection Limit : 0.1 mg/kg.

Tested Item: GRAPAGE/GRAPVIN GRAPE GUARD

Note :-

1. mg/kg = milligram per kilogram.
2. ND = Not Detected.
3. Testing has been subcontracted to SGS approved lab.
4. Testing has been performed as per client's request.



TEST REPORT

Report No. : MAN:HL:1048003871

DATE : 28th May, 2019



Sample as Received (Grouped Samples)



***** END OF REPORT*****